

# Machine Design Under Uncertainty



Founded 1870 | Rolla, Missouri



MISSOURI UNIVERSITY OF SCIENCE AND TECHNOLOGY




# Outline

- Uncertainty in mechanical components
- Why consider uncertainty
- Basics of uncertainty
- Uncertainty analysis for machine design
- Examples
- Conclusions

# Uncertainty in Mechanical Components

- A simply-supported beam has a diameter of 1.25 in. The deflection at  $x = 10$  in should be less than  $\delta = 0.00375$  in. Can the requirement be met?
- Everything is modeled perfectly.
- In reality, the forces and dimensions are random.
- So is the deflection.





# Where Does Uncertainty Come From?

- Manufacturing impression
  - Dimensions of a component
  - Material properties
- Environment
  - Loading
  - Temperature
  - Different users




# Why Consider Uncertainty?

- We know the true solution.
- We know the effect of uncertainty.
- We can make more reliable decisions.

# How Do We Model Uncertainty?



- We use probability distributions to model parameters with uncertainty.



# Probability Distribution


- With more samples, we can draw a histogram.
- If y-axis is frequency and the number of samples is infinity, we get a probability density function (PDF)  $f(x)$ .
- The probability of  $a \leq X \leq b$ .

$$\Pr\{a \leq X \leq b\} = \int_a^b f(x)dx$$



# Normal Distribution

- $X \sim N(\mu, \sigma^2)$
- $F(x) = \Pr\{X < x\}$ :  
cumulative distribution  
function (CDF)
- $\Pr\{a < X < b\} = F(b) - F(a)$
- $\Pr\{X < x\} = \Phi\left(\frac{x - \mu_Y}{\sigma_Y}\right)$
- $\Pr\{X > x\} = 1 - \Pr\{X <$







# More about Standard Deviation $\sigma$ (std)

- It indicates how data spread around the mean.
- It is always non-negative.
- High std means
  - High dispersion
  - High uncertainty
  - High risk



# More Than One Random Variables

- If
  - $X_i \sim N(\mu_i, \sigma_i^2)$
  - $X_i$  ( $i = 1, 2, \dots, n$ ) are independent
  - $Y = c_0 + c_1X_1 + c_2X_2 + \dots + c_nX_n$
  - $c_i$  ( $i = 1, 2, \dots, n$ ) are constants.
- Then
  - $Y \sim N(\mu_Y, \sigma_Y^2)$
  - $\mu_Y = c_0 + c_1\mu_1 + c_2\mu_2 + \dots + c_n\mu_n$
  - $\sigma_Y = \sqrt{c_1^2\sigma_1^2 + c_2^2\sigma_2^2 + \dots + c_n^2\sigma_n^2}$

# Reliability

- Reliability is the ability of a component to perform its intended function without failure.
- Reliability is measure by the probability of such ability.
- $R = \Pr\{g(\mathbf{X}) > 0\}$ 
  - $\mathbf{X}$ : random variables
  - $g(\cdot)$ : limit-state function
  - If  $g(\mathbf{X}) < 0$ , a failure occurs
- Probability of failure  $p_f = \Pr\{g(\mathbf{X}) < 0\} = 1 - R$

# First Order Second Moment Method (FOSM)

- Assume  $X_i \sim N(\mu_i, \sigma_i^2)$  and are independent
- First order Taylor expansion

$$Y = g(\mathbf{X}) \approx g(\boldsymbol{\mu}) + \sum_{i=1}^n \frac{\partial g}{\partial X_i} (X_i - \mu_i)$$


$$\boldsymbol{\mu} = (\mu_1, \mu_2, \dots, \mu_n)$$

- $Y \sim N(\mu_Y, \sigma_Y^2)$ ,  $\mu_Y = g(\boldsymbol{\mu})$ ,  $\sigma_Y^2 = \sum_{i=1}^n \left( \frac{\partial g}{\partial X_i} \right)^2 \sigma_i^2$

- $p_f = \Pr\{g(\mathbf{X}) < 0\} = \Phi\left(\frac{-\mu_Y}{\sigma_Y}\right)$

# Monte Carlo Simulation (MCS)\*

## A sampling-based simulation method



\*This topic is optional.



# Step 1: Sampling on random variables

- Generate samples of input random variables according to their distributions.
- For example, for  $X_i \sim N(\mu_i, \sigma_i^2)$ , samples can be generated by Matlab.
  - Matlab `normrnd( $\mu_i, \sigma_i, 1, N$ )` produces a row vector of  $N$  random samples.
  - Excel can also be used.



## Step 2: Obtain Samples of Output

- Suppose  $N$  sets of random variables have been generated

$$\mathbf{x}_i = (x_{i1}, x_{i2}, \dots, x_{in}), i = 1, 2, \dots, N$$

$N$  is the number of simulations

- Then samples of output  $s$  are calculated a

$$y_i = g(\mathbf{x}_i)$$

## Step 3: Statistic Analysis on output

- Mean  $\mu_Y = \frac{1}{N} \sum_{i=1}^N y_i$
- Standard deviation  $\sigma_Y = \sqrt{\frac{1}{N-1} \sum_{i=1}^N (y_i - \mu_i)^2}$
- The probability of failure  $p_f = \frac{N_f}{N}$   
 $N_f$  is the number of failures.  
 $N_f = \text{number of } y_i < 0, i = 1, 2, \dots, N$






# FORM vs MCS

- FORM is more efficient
- FORM may not be accurate when a limit-state function is highly nonlinear
- MCS is very accurate if the sample size is sufficiently large
- MCS is not efficient

# Example - FOSM



- $L = 100$  in,  $t = 2$  in,  $w = 4$  in,  $E = 30 \times 10^6$  psi
- $\mathbf{X} = (P_x, P_y)$ ,  $P_x \sim N(500, 60^2)$  lb,  $P_y \sim N(1000, 100^2)$  lb,  $P_x$  and  $P_y$  are independent
- Allowable deflection  $D_0 = 3$  in

- $$Y = g(\mathbf{X}) = D_0 - \frac{4L^3}{Ewt} \sqrt{\left(\frac{P_x}{w^2}\right)^2 + \left(\frac{P_y}{t^2}\right)^2}$$

- $$p_f = \Pr\{Y = g(\mathbf{X}) < 0\}$$

# Example - FOSM

$$\bullet \mu_Y = g(\boldsymbol{\mu}) = D_0 - \frac{4L^3}{Ewt} \sqrt{\left(\frac{P_x}{w^2}\right)^2 + \left(\frac{P_y}{t^2}\right)^2} = 3 -$$

$$\frac{4(100^3)}{30 \times 10^6 (4)(2)} \sqrt{\left(\frac{500}{4^2}\right)^2 + \left(\frac{1000}{2^2}\right)^2} = 0.6708$$

$$\bullet \frac{\partial g}{\partial P_x} = -\frac{4L^3}{Ewt} \frac{P_x}{w^4} \frac{1}{A} = -3.7268e - 03$$

$$\bullet \frac{\partial g}{\partial P_y} = -\frac{4L^3}{Ewt} \frac{P_y}{t^4} \frac{1}{A} = -4.6585e - 04$$


$$\text{where } A = \sqrt{\left(\frac{P_x}{w^2}\right)^2 + \left(\frac{P_y}{t^2}\right)^2}$$

# Example - FOSM

$$\bullet \sigma_Y = \sqrt{\left(\frac{\partial g}{\partial P_x}\right)^2 \sigma_{P_x}^2 + \left(\frac{\partial g}{\partial P_y}\right)^2 \sigma_{P_y}^2} = 0.2284$$

$$\bullet p_f = \Phi\left(\frac{-\mu_Y}{\sigma_Y}\right) = \Phi\left(\frac{-0.6708}{0.2284}\right) = \\ \Phi(-2.9367) = 1.70 \times 10^{-3}$$

# Example - MCS





- $L = 100$  in,  $t = 2$  in,  $w = 4$  in,  $E = 30 \times 10^6$  psi
- $\mathbf{X} = (P_x, P_y)$ ,  $P_x \sim N(500, 100^2)$  lb,  
 $P_y \sim N(1000, 100^2)$  lb,  $P_x$  and  $P_y$  are independent
- Allowable deflection  $D_0 = 3$  in

- $$g(\mathbf{X}) = D_0 - \frac{4L^3}{Ewt} \sqrt{\left(\frac{P_x}{w^2}\right)^2 + \left(\frac{P_y}{t^2}\right)^2}$$



- $$p_f = \Pr\{g(\mathbf{X}) < 0\}$$

# 100 and 1000 Simulations



# 1e5 Simulations


- More simulations, More accurate result




# Reliability –Based Design (RBD)

Design without  
considering uncertainty:  
Low reliability

- Nominal design point
- Actual design points



Design with considering  
uncertainty: high  
reliability







# RBD

- RBD ensures that a design has the probability of failure less than an acceptable level, and
- therefore ensures that events that lead to catastrophe are extremely unlikely.
- RBD is achieved by maximizing cost and maintaining reliability at a required level.



# Conclusions

- For important mechanical components in important applications,
- a factor of safety may not be sufficient to account for uncertainties;
- it is imperative to consider reliability.
- Uncertainty can be modeled probabilistically.
- Reliability can be estimated by FOSM and MCS.